



SMITHERS

QUALITY ASSESSMENTS

CERTIFICATE OF APPROVAL

This is to Certify that the Quality Management System of:

Clinton Aluminum Distribution, Inc.

2811 Eastern Road

Norton, OH 44203

(Page 1 of 2; see Appendix)

has been assessed and approved by Smithers Quality Assessments, Inc., to the following quality management system standards and requirements:

ISO 9001:2015 without Design

The Quality Management System is Applicable to:

Processor and stocking distributor of prime non-ferrous metals (primarily aluminum and stainless steel). Provider of value-added services to meet customer specifications.

Approval Certificate Number: 02.340.2

Original Approval: December 6, 2002

Current Certificate: November 15, 2020

Certificate Expires: November 14, 2023



The use of the accreditation mark indicates accreditation in respect of those activities covered by the above certificate number.

on behalf of SQA - J. Michael Hochschwender, CEO

The approval is subject to the company maintaining its system to the required standards which will be monitored by Smithers Quality Assessments, Inc., 121 S. Main St., Akron, Ohio 44308, USA



APPENDIX A
TO THE CERTIFICATE
OF REGISTRATION NO.: 02.340.2



Page 2 of 2

SMITHERS QUALITY ASSESSMENTS, INC.

Site:

Clinton Aluminum Distribution, Inc.
2811 Eastern Road
Norton, OH 44203

Scope of activities: Cutting, blanking and processing of bulk materials.

The above site is certified by Smithers Quality Assessments, Inc. with regard to ISO 9001:2015 without Design. The following locations are included utilizing a Multi-site (with Sampling) approach.

Location(s):

Clinton Aluminum Distribution, Inc.
400 Freedom Lane
Janesville, WI 53545

Scope of activities: Receiving, cutting, shipping.

Applicable Standard: ISO 9001:2015 without Design

This appendix applies only to those sites listed above. As other sites are assessed and approved, or as sites already approved are removed from active services, this appendix will be amended to show the current status. Sites not listed on this appendix shall not be viewed as approved.